

FOR:

STATE OF ALABAMA

DEPTARTMENT OF FINANCE DIVISION OF PURCHASING

INVITATION TO BID

HEATING AND AIR COND MAINT

REQ. AGENCY : 010022

DEPARTMENT OF FINANCE

AGENCY REQ. NO.

T-NUMBER : TA161 DATE ISSUED : 08/23/10

VENDOR NO.
VENDOR PHONE NO.
SNAP REQ. NO.
BUYER NAME : 1443551 : RAY BRESSLER

BUYER PHONE NO. : (334) 242-4670-PURCHASING PHONE NO: (334) 242-7250

BID MUST BE RECEIVED BEFORE: DATE: 09/08/10 TIME: 5:00 PM

BIDS WILL BE PUBLICLY OPENED: DATE: 09/09/10 TIME: 10:00 AM

FAX NUMBER

TO BE COMPLETED BY VENDOR

| INFORMATION IN THIS SECTION OF TYPED W | ON SHOULD BE PROVIDED, ITH ORIGINAL SIGNATURE | AS APPROPRIATE. BID RESPONSE AND NOTARIZATION. |
|---|--|--|
| 1. DELIVERY: CAN BE MADE _ | DAYS OR | WEEKS AFTER RECEIPT OF ORDER |
| 2. TERMS: | (DISCOUNTS ARE TAKEN W | ITHOUT REGARD TO DATE OF PAYMENT.) |
| 3. PRICE VALID FOR ACCEPTA | NCE WITHIN | _ DAYS. |
| 4. VENDOR QUOTATION REFERE (THIS NUMBER WILL APPEA | | |
| 5. E-MAIL ADDRESS: | | |
| INTERNET WEBSITE: | | |
| 6. GENERAL CONTRACTOR'S LI | CENSE NO: | |
| TYPE OF G.C. LICENSE: _ | | |
| | NT. | : ***** ISTRUCTIONS" ON PAGE 2, TO INCLUDE |
| | 10. | |
| US MAIL | | COURIER |
| STATE OF ALABAM DEPARTMENT OF F DIVISION OF PUR P O BOX 302620 MONTGOMERY, AL | INANCE CHASING | STATE OF ALABAMA DIVISION OF PURCHASING RSA UNION BUILDING 100 N. UNION ST., SUITE 192 MONTGOMERY, AL 36104 |
| I HAVE READ THE ENTIRE BID I HERBY AFFIRM I HAVE NOT : | BEEN IN ANY AGREEMENT | ON REQUIRED EACH ITEM OFFERED AT THE PRICE QUOTED. OR COLLUSION AMONG BIDDERS IN TO BID AT A FIXED PRICE OR TO |
| SWORN TO AND | FEIN OR SSN | AUTHORIZED SIGNATURE (INK) |
| SUBSCRIBED BEFORE ME THIS | COMPANY NAME | TYPE/PRINT AUTHORIZED NAME |
| DAY OF | MAIL ADDRESS | TITLE |
| NOTARY PUBLIC | CITY, STATE, ZIP | TOLL FREE NUMBER |
| TEDM EVD. | | |

PHONE INCLUDING AREA CODE

STANDARD TERMS & CONDITIONS

VENDOR NAME :

PAGE

2

INVITATION TO BID 09/09/10 TIME: 10:00 AM

RETURN DATE: 09/08/10 TIME: 5:00 PM

AUTHORITY:

THE DEPARTMENT OF FINANCE CODE OF ADMINISTRATIVE PROCEDURE, CHAPTER 355-4-1 EFFECTIVE DECEMBER 20, 2001 IS INCORPORATED BY REFERENCE AND MADE A PART OF T HIS DOCUMENT. TO RECEIVE A COPY CALL (334)242-7250, OR OUR WEBSITE WWW.PURCHASING.ALABAMA.GOV.

INFORMATION AND ASSISTANCE TO MINORITY AND WOMEN-OWNED BUSINESSES IN ACQUIRING M/WBE CERTIFICATION MAY BE OBTAINED FROM THE OFFICE OF MINORITY BUSINESS ENTERPRISE, 1-800-447-4191.

BID (ITB) RESPONSE INSTRUCTIONS REV: 07/15/10

- TO SUBMIT A RESPONSIVE BID, READ THESE INSTRUCTIONS, ALL TERMS, CONDITIONS AND SPECIFICATIONS.
- BID ENVELOPES/PACKAGES/BOXES MUST BE IDENTIFIED ON FRONT, PREFERABLY LOWER LEFT CORNER AND BE VISIBLE WITH THE BID NUMBER AND OPENING DATE. EACH INDIVIDUAL BID (IDENTIFIED BY A UNIQUE BID NUMBER) MUST BE SUBMITTED IN A SEPARATE ENVELOPE. RESPONSES TO MULTIPLE BID NUMBERS SUBMITTED IN THE SAME ENVELOPE/COURIER PACKAGE, THAT ARE NOT IN SEPARATE ENVELOPES PROPERLY IDENTIFIED, WILL BE REJECTED. THE DIVISION OF PURCHASING DOES NOT ASSUME RESPONSIBILITY FOR LATE BIDS FOR ANY REASON INCLUDING THOSE DUE TO POSTAL, OR COURIER SERVICE. BID RESPONSES MUST BE IN THE DIVISION OF PURCHASING OFFICE PRIOR TO THE "RECEIVE DATE AND TIME" INDICATED ON THE BID.
- BID RESPONSES (PAGE 1, PRICE SHEET AND ADDENDUMS (WHEN SIGNATURE IS REQUIRED)) MUST BE IN INK OR TYPED ON THIS DOCUMENT. OR EXACT FORMAT WITH SIGNATURES BEING HANDWRITTEN ORIGINALS IN INK (PERSON SIGNING BID, NOTARY, AND NOTARY EXPIRATION), OR THE BID WILL BE REJECTED. UNLESS INDICATED IN THE BID, ALL PRICE PAGES MUST BE COMPLETED AND RETURNED. IF AN ITEM IS NOT BEING BID, IDENTIFY IT AS NB (NO-BID). PAGES SHOULD BE SECURED. THE DIVISION OF PURCHASING DOES NOT ASSUME RESPONSIBILITY FOR MISSING PAGES. FAXED BID RESPONSES WILL NOT BE ACCEPTED.
- THE UNIT PRICE ALWAYS GOVERNS REGARDLESS OF THE EXTENDED AMOUNT. A UNIT PRICE CHANGE ON A LINE MUST BE INITIALED BY THE PERSON SIGNING THE BID, OR THAT LINE WILL BE REJECTED. THIS INCLUDES A CROSS-OUT, STRIKE-OVER, INK-OVER, WHITE-OUT, ERASURE, OR ANY OTHER METHOD CHANGING THE PRICE.
- THE DIVISION OF PURCHASING IS NOT RESPONSIBLE FOR MISINTERPRETATION OF DATA FAXED FROM THIS OFFICE.
- THE DIVISION OF PURCHASING REQUIRES AN ORIGINAL AND A MINIMUM OF ONE COMPLETE EXACT COPY (TO INCLUDE SIGNATURE AND NOTARY) OF THE INVITATION-TO-BID RESPONSE. THE ORIGINAL AND THE COPY SHOULD BE SUBMITTED TOGETHER AS A BID PACKAGE. FAILURE TO MARK RESPONSES AS "ORIGINAL" AND/OR "COPY" COULD RESULT IN THE ENTIRE BID RESPONSE BEING REJECTED.
- AN IMPROPERLY SUBMITTED BID, LATE BID, OR BID THAT IS CANCELLED ON OR BEFORE THE OPENING DATE WILL BE HELD FOR 90 DAYS AND THEN DESTROYED. THE BID MUST BE RETRIEVED DURING REGULAR WORK HOURS, MONDAY FRIDAY, EXCEPT STATE HOLIDAYS. AFTER THE BID IS DESTROYED, THE DIVISION OF PURCHASING ASSUMES NO RESPONSIBILITY FOR THE DOCUMENT.

DISQUALIFIED/CANCELLED BID

BIDS THAT ARE IMPROPERLY SUBMITTED OR RECEIVED LATE WILL BE A RESPONSE FOR RECORD, BUT WILL NOT BE RETURNED OR A NOTIFICATION MAILED.

THE FOLLOWING IS A PARTIAL LIST WHEREBY A BID RESPONSE WILL BE DISQUALIFIED:

BID NUMBER NOT ON FACE OF ENVELOPE/COURIER PACKAGE/BOX RESPONSES TO MULTIPLE BID NUMBERS IN SAME ENVELOPE NOT PROPERLY IDENTIFIED

BID RECEIVED LATE

BID NOT SIGNED/NOT ORIGINAL SIGNATURE

BID NOT NOTARIZED/NOT ORIGINAL SIGNATURE OF NOTARY AND/OR NO NOTARY EXPIRATION

NOTARIZED OWN SIGNATURE

REQUIRED INFORMATION NOT SUBMITTED WITH BID FAILURE TO SUBMIT THE ORIGINAL BID AND A COMPLETE EXACT COPY

CERTIFICATION PURSUANT TO ACT NO. 2006-557

ALABAMA LAW (SECTION 41-4-116, CODE OF ALABAMA 1975) PROVIDES THAT EVERY BID SUBMITTED AND CONTRACT ALABAMA LAW (SECTION 41-4-116, CODE OF ALABAMA 1975) PROVIDES THAT EVERY BID SUBMITTED AND CONTRACT EXECUTED SHALL CONTAIN A CERTIFICATION THAT THE VENDOR, CONTRACTOR, AND ALL OF ITS AFFILIATES THAT MAKE SALES FOR DELIVERY INTO ALABAMA OR LEASES FOR USE IN ALABAMA ARE REGISTERED, COLLECTING, AND REMITTING ALABAMA STATE AND LOCAL SALES, USE, AND/OR LEASE TAX ON ALL TAXABLE SALES AND LEASES INTO ALABAMA. BY SUBMITTING THIS BID, THE BIDDER IS HEARBY CERTIFYING THAT THEY ARE IN FULL COMPLIANCE WITH ACT NO. 2006-557, THEY ARE NOT BARRED FROM BIDDING OR ENTERING INTO A CONTRACT PURSUANT TO 41-4-116, AND ACKNOWLEDGES THAT THE AWARDING AUTHORITY MAY DECLARE THE CONTRACT VOID IF THE CERTIFICATION IS FALSE. SPECIAL TERMS & CONDITIONS

VENDOR NAME :

VENDOR NUMBER:

ITB NO.

: 10-X-2220012 : 09/09/10 TIME: 10:00 AM INVITATION TO BID OPEN DATE

T-NUMBER TA161

RETURN DATE: 09/08/10 TIME: 5:00 PM

PAGE

3

VENDOR REGISTRATION AND FEE PAYMENT ONLINE

EFFECTIVE SEPTEMBER 1, 2010, VENDORS MUST REGISTER ONLINE TO RECEIVE NOTIFICATION OF BIDS. GO TO WWW.PURCHASING.ALABAMA.GOV TO REGISTER. BIDS WILL NOT BE ACCEPTED FROM NON-REGISTERED VENDORS. A VENDOR'S REGISTRATION MUST BE MAINTAINED THROUGHOUT THE LIFE CYCLE OF AN AWARDED CONTRACT, TO INCLUDE RENEWAL PERIODS. AT THE TIME OF REGISTRATION, VENDOR MUST PAY A BIENNIAL REGISTRATION FEE. PAYMENT MUST BE MADE BY CREDIT CARD, DEBIT CARD, OR BY ELECTRONIC CHECK.

INTENT TO AWARD

EFFECTIVE MAY 1, 2008, THE STATE OF ALABAMA - DIVISION OF PURCHASING WILL ISSUE AN 'INTENT TO AWARD' BEFORE A FINAL AWARD IS MADE. THE 'INTENT TO AWARD' WILL CONTINUE FOR A PERIOD OF FIVE (5) CALENDAR DAYS, AFTER WHICH A PURCHASE ORDER WILL BE PRODUCED. UPON FINAL AWARD, ALL RIGHTS TO PROTEST ARE FORFEITED. A DETAILED EXPLANATION OF THIS PROCESS MAY BE REVIEWED IN THE ALABAMA ADMINISTRATIVE CODE - CHAPTER 355-4-1(14) CHAPTER 355-4-1(14).

ALTERNATE BID RESPONSE

UNLESS STATED ELSEWHERE IN THIS INVITATION-TO-BID (ITB) THE STATE OF ALABAMA WILL ACCEPT AND EVALUATE ALTERNATE BID SUBMITTALS ON ANY ITB'S. ALTERNATE BID RESPONSES WILL BE EVALUATED ACCORDING TO THE REQUIREMENTS AS ALL OTHER RESPONSES TO THIS ITB.

INTERNET WEBSITE LINK'S

INTERNET AND/OR WEBSITE LINKS WILL NOT BE ACCEPTED IN BID RESPONSES AS A MEANS TO SUPPLY ANY REQUIREMENTS STATED IN THIS ITB (INVITATION-TO-BID).

PRODUCT DELIVERY, RECEIVING AND ACCEPTANCE

IN ACCORDANCE WITH THE UNIVERSAL COMMERCE CODE (CODE OF ALABAMA, TITLE 7), AFTER DELIVERY, THE STATE OF ALABAMA HAS THE RIGHT TO INSPECT ALL PRODUCTS BEFORE ACCEPTING. THE STATE WILL INSPECT PRODUCTS IN A REASONABLE TIMEFRAME. SIGNATURE ON A DELIVERY DOCUMENT DOES NOT CONSTITUTE ACCEPTANCE BY THE STATE. THE STATE WILL ACCEPT PRODUCTS ONLY AFTER SATISFACTORY INSPECTION.

SALES TAX EXEMPTION

PURSUANT TO THE CODE OF ALABAMA, 1975, TITLE 40-23-4 (A) (11), THE STATE OF ALABAMA IS EXEMPT FROM PAYING SALES TAX. AN EXEMPTION LETTER WILL BE FURNISHED UPON REQUEST.

INVOICES

INQUIRIES CONCERNING PAYMENT AFTER INVOICES HAVE BEEN SUBMITTED ARE TO BE DIRECTED TO THE RECEIVING AGENCY, NOT THE DIVISION OF PURCHASING

BID RESPONSES AND BID RESULTS

UNEVALUATED BID RESPONSES (NOT BID RESULTS) ARE AVAILABLE ON OUR WEB SITE AT WWW.PURCHASING.ALABAMA.GOV. BID RESULTS WILL BE MADE AVAILABLE FOR REVIEW IN THE DIVISION OF PURCHASING OFFICE, BUT ONLY AFTER THE BID HAS BEEN AWARDED. WE DO NOT FAX OR MAIL COPIES OF BID RESULTS. IF A VENDOR WISHES TO REVIEW BID RESULTS IN OUR OFFICE, THEY SHOULD FAX THEIR REQUEST TO REVIEW THE BID TWO DAYS IN ADVANCE TO THE "BID REVIEW CLERK" AT (334) 242-4419. BE SURE TO REFERENCE THE BID NUMBER.

FOREIGN CORPORATION - CERTIFICATE OF AUTHORITY

ALABAMA LAW PROVIDES THAT A FOREIGN CORPORATION (AN OUT-OF-STATE

VENDOR NAME :

VENDOR NUMBER:

TTB NO. : 10-X-2220012 OPEN DATE : 09/09/10 TIME: 10:00 AM

T-NUMBER TA161

RETURN DATE: 09/08/10 TIME: 5:00 PM

PAGE

4

COMPANY/FIRM) MAY NOT TRANSACT BUSINESS IN THE STATE OF ALABAMA UNTIL IT OBTAINS A CERTIFICATE OF AUTHORITY FROM THE SECRETARY OF STATE.
SECTION 10-2B-15.01, CODE OF ALABAMA 1975. TO OBTAIN FORMS FOR A
CERTIFICATE OF AUTHORITY, CONTACT THE SECRETARY OF STATE, CORPORATIONS DIVISION, (334) 242-5324. THE CE THE VENDOR FROM SUBMITTING A BID. THE CERTIFICATE OF AUTHORITY DOES NOT KEEP

BID IDENTIFICATION

REFERENCE PAGE 2, ITEM 2. DUE TO THE POSTAL SERVICE PUTTING BAR CODE LABELS ON ENVELOPES, IT CONCEALS THE BIO NUMBER AND DATE IF THE VENDOR HAS WRITTEN THEM OTHER THAN THE LOWER LEFT CORNER, THEREFORE THE BID WOULD BE REJECTED FOR NOT BEING PROPERLY IDENTIFIED.

AWARD:

EACH ITEM MUST BE PRICED SEPARATELY. HOWEVER, AN "ALL OR NONE" AWARD MAY BE MADE TO INSURE COMPATIBILITY AND/OR MAINTENANCE INTEGRITY WHERE APPLICABLE. AWARD WILL BE MADE TO THE LOWEST RESPONSIBLE BIDDER(S) MEETING ALL SPECIFICATIONS.

ASSIGNMENT OF CONTRACT:

TO ASSIGN, SUBLET OR TRANSFER ANY CONTRACT RESULTING FROM THIS SOLICITATION, THE VENDOR'S WRITTEN REQUEST MUST BE APPROVED BY THE STATE PURCHASING DIRECTOR.

DELIVERY AND INSTALLATION:

BID IS TO INCLUDE COST OF TRANSPORTATION, UNLOADING, INSTALLATION AND REMOVAL OF DEBRIS. DROP SHIPMENTS ARE NOT ACCEPTABLE. TITLE WILL CHANGE UPON RECEIPT OF SATISFACTORY DELIVERY AND INSTALLATION.

F.O.B. DESTINATION: F.O.B. DESTINATION IS THE LOCATION WHERE MERCHANDISE IS DELIVERED AND UNLOADED ON A RECEIVING DOCK, IF AVAILABLE, TO ANY STATE OR LOCAL GOVERNMENT AGENCY AND THE CHANGE OF TITLE TAKES PLACE. THE VENDOR IS LIABLE FOR FREIGHT CHARGES, RISK OF LOSS OR DAMAGE TO THE MERCHANDISE UP TO THE DESTINATION.

BID IS F.O.B. DESTINATION. ANY FREIGHT CHARGES MUST BE INCLUDED IN THE BID PRICES.

CONTRACT PERIOD:

CONTRACT PERIOD:
ESTABLISH A 12 MONTH CONTRACT WITH AN OPTION TO EXTEND FOR A SECOND,
AND THIRD 12 MONTH PERIOD WITH THE SAME PRICING, TERMS AND CONDITIONS.
THE SECOND AND THIRD 12 MONTH PERIOD, IF AGREED BY BOTH PARTIES,
WOULD BEGIN THE DAY AFTER THE FIRST OR SECOND 12 MONTH PERIOD
EXPIRES. ANY SUCCESSIVE EXTENSION MUST HAVE WRITTEN APPROVAL OF BOTH
THE STATE AND VENDOR NO LATER THAN 30 DAYS PRIOR TO EXPIRATION OF THE PREVIOUS 12 MONTH PERIOD.

NON-APPROPRIATION OF FUNDS:

NON-APPROPRIATION OF FUNDS:

CONTINUATION OF ANY AGREEMENT BETWEEN THE STATE AND A BIDDER BEYOND A FISCAL YEAR IS CONTINGENT UPON CONTINUED LEGISLATIVE APPROPRIATION OF FUNDS FOR THE PURPOSE OF THIS BID AND ANY RESULTING AGREEMENT. NON-AVAILABILITY OF FUNDS AT ANY TIME SHALL CAUSE ANY AGREEMENT TO BECOME VOID AND UNENFORCEABLE AND NO LIQUIDATED DAMAGES SHALL ACCRUE TO THE STATE AS A RESULT. THE STATE WILL NOT INCUR LIABILITY BEYOND THE PAYMENT OF ACCRUED AGREEMENT PAYMENT.

ANY PROVISION OF A CONTRACT RESULTING FROM THIS BID TO THE CONTRARY NOTWITHSTANDING, IN THE EVENT OF FAILURE OF THE STATE TO MAKE PAYMENT HEREUNDER AS A RESULT OF PARTIAL UNAVAILABILITY, AT THE TIME SUCH PAYMENT IS DUE, OF SUCH SUFFICIENT REVENUES OF THE STATE TO MAKE SUCH PAYMENT (PRORATION OF APPROPRIATED FUNDS FOR THE STATE HAVING BEEN DECLARED BY THE GOVERNOR PURSUANT TO SECTION 41-4-90 OF THE CODE OF

INVITATION TO BID

SPECIAL TERMS & CONDITIONS

VENDOR NAME :

VENDOR NUMBER:

TTB NO. : 10-X-2220012

OPEN DATE : 09/09/10 TIME: 10:00 AM

T-NUMBER : TA161 INVITATION TO BID

RETURN DATE: 09/08/10 TIME: 5:00 PM

PAGE 5

ALABAMA 1975), THE CONTRACTOR SHALL HAVE THE OPTION, IN ADDITION TO THE OTHER REMEDIES OF THE CONTRACT, OF RENEGOTIATING THE CONTRACT (EXTENDING OR CHANGING PAYMENT TERMS OR AMOUNTS) OR TERMINATING THE CONTRACT.

QUALITY OF MATERIALS AND LABOR:

QUALITY OF MATERIALS AND LABOR.

MATERIALS USED THAT ARE NOT OTHERWISE SPECIFIED SHALL BE THE KIND AND QUALITY CONSISTENT WITH THE TRADE PRACTICE FOR SUCH WORK AND SHALL COMPLY WITH ALL LOCAL CODES. ALL LABOR SHALL BE WELL EXPERIENCED IN THIS TYPE WORK AND IT SHALL BE COMPLETED IN A PROFESSIONAL MANNER.

BLANK LINES:

TO EVALUATE THE BID IN AN EFFICIENT MANNER, THE VENDOR SHOULD FILL-IN ALL BLANK LINES APPLICABLE TO A SPECIFIC COMMODITY DESCRIPTION.

REQUESTED INFORMATION: ANY ADDITIONAL INFORMATION REQUESTED FROM A VENDOR MUST BE FURNISHED WITHIN TEN (10) DAYS FROM RECEIPT OF REQUEST.

SPECIAL TERMS & CONDITIONS VENDOR NAME :

VENDOR NUMBER: ITB NO. : 10-X-2220012
OPEN DATE : 09/09/10 TIME: 10:00 AM
T-NUMBER : TA161
RETURN DATE: 09/08/10 TIME: 5:00 PM INVITATION TO BID

PAGE 6

THE FOLLOWING CONFERENCES WILL BE HELD

CONFERENCE LOCATION

DEPT FINANCE/RISK MGT CONFERENCE ROOM/ 2ND FLOOR 777 S LAWRENCE ST MONTGOMERY AL 36104 MANDATORY SITE VISIT DATE: 09/01/10 TIME: 9:00 AM

ATTACHMENTS VENDOR NAME :

VENDOR NUMBER: ITB NO. : 10-X-2220012
OPEN DATE : 09/09/10 TIME: 10:00 AM
T-NUMBER : TA161
RETURN DATE: 09/08/10 TIME: 5:00 PM INVITATION TO BID

PAGE 7

DATE: SEPTEMBER 1, 2010 TIME: 9:00 AM

LOCATION: 777 SOUTH LAWRENCE STREET 2ND FLOOR RECEPTION AREA

MONTGOMERY, AL

VENDOR REP. SIGNATURE PRINT NAME

AGENCY REP. SIGNATURE PRINT NAME

VENDORS SHOULD BRING THE LIST OF EQUIPMENT TO THE SITE VISIT TO VERIFY ITS ACCURACY.

FAILURE TO ATTEND THE MANDATORY SITE VISIT AND OBTAIN SIGNATURES WILL RESULT IN BID REJECTION.

VENDOR NUMBER:

: 10-X-2220012 ITB NO.

QTR

PAGE INVITATION TO BID OPEN DATE : 09/09/10 TIME: 10:00 AM

T-NUMBER TA161

RETURN DATE: 09/08/10 TIME: 5:00 PM

8

EXTENDED LINE COMMODITY/SERVICE DESCRIPTION QUANTITY UNIT UNIT PRICE AMOUNT NO.

UNLESS SPECIFIED OTHERWISE BELOW: SHIP TO: 010020 / 010M03
DEPARTMENT OF FINANCE/RISK MANG DIVISION OF RISK MANAGEMENT

777 S LAWRENCE ST SUITE 200

MONTGOMERY

36104

00001 COMMODITY CODE: 910-36-058004 MAINTENANCE, AIR CONDITIONING PER ATTACHED TERMS AND CONDITIONS.

HEATING AND AIR CONDITIONING SERVICES TO INCLUDE ALL OF THE FOLLOWING LOCATIONS: 770 S. MCDONOUGH STREET

771 S. LAWRENCE STREET 777 S. LAWRENCE STREET

PLEASE NOTE PLEATED FILTERS WILL BE USED IN ALL AIR HANDLING UNITS THAT ARE CAPABLE OF ACCEPTING THEM.

A QUARTERLY MAINTENANCE ON HEATING AND AIR CONDITIONING SERVICE WILL INCLUDE THE FOLLOWING:

- 1. INSPECTION AND TUNE UP
- 2. REPLACE DISPOSABLE FILTERS AND CLEAN WASHABLE FILTERS
- CHECK OPERATING PRESSURES AND CHARGE WITH REFRIGERANT (FREON)
- 4. CHECK THERMOSTAT ACCURACY
 5. CLEAN AND INSPECT INDOOR AND OUTDOOR COILS
- 6. CLEAN AND DRAIN PAN AND LINES
- 7. OIL AND GREASE MOTORS

IN ADDITION THE BOILER AND MACHINERY EQUIPMENT SERVICE SHOULD INCLUDE THE FOLLOWING:

- A. THE HEATING SEASON START-UP CONFIRM-ATION AND INSPECTION.
- STARTING THE BOILER AND CONFIRMING
- THE OPERATING STATUS.

 2. RECORD THE OPERATING CONDITIONS OF THE BOILER AND DISCUSS WITH MANAGE-
- MENT PERSONNEL.
 3. CHECK ALL CONTROLS FOR PROPER OPERATION.
- CHECK THE BURNER COMPOSITION FOR SIGNS OF EXCESSIVE SMOKE AND ADJUST IF REQUIRED.
- 5. ANALYŽE FUEL GASES VIA A COMBUSTION ANALYSIS.
- 6. INSPECT AND TEST THE RELIEF VALUE FOR PROPER OPERATION. 7. CHECK THE LOW WATER-FUEL SHUTOFF
- 8. CHECK ALL MOTORS
- CHECK THE ENTERING AND LEAVING HOT WATER OR STEAM TEMPERATURE
- 10. CHECK AND CLEAN THE FUEL FILTERS

PAGE TOTAL

VENDOR NUMBER:

ITB NO.

: 10-X-2220012 : 09/09/10 TIME: 10:00 AM PAGE INVITATION TO BID OPEN DATE

T-NUMBER TA161 RETURN DATE: 09/08/10 TIME: 5:00 PM 9

LINE EXTENDED

COMMODITY/SERVICE DESCRIPTION QUANTITY UNIT UNIT PRICE AMOUNT NO.

- B. THE ANNUAL EQUIPMENT SHUTDOWN INSPECTION
- 1. INSPECT THE BOILER CASINGS FOR SIGNS
- OF WARPING, ALIGNMENT OR OVERHEATING
 2. INSPECTING THE SUPPORTING MEMBER FOR PROPER ALIGNMENT, SAGGING, OR SHIFTING.
- SHIFTING.

 3. WATER WALL TUBES AND ACCESSIBLE
 GENERATOR TUBES IN THE FIREBOX AREA
 SHOULD BE INSPECTED FOR ALIGNMENT,
 CORROSION, EROSION, BULGES AND
 DETERIORATE WELDS.

 4. INSPECTING THE INTERNAL SURFACES OF
 DRUMS AND HEADS FOR PITTING OR
 SURFACE IRREGULARITIES.

 5. BRUSHING AND INSPECTING EACH TUBE
 FOR PITTING, EROSION, CORROSION
 AND EXCESSIVE SCALE BUILDUP.

 6. CLEANING AND INSPECTING THE SHELL

- 6. CLEANING AND INSPECTING THE SHELL BETWEEN THE TUBES AND END HOLES
- 7. CLEANING AND REPLACING OIL NOZZLES AND FILTERS
- 8. VERIFYING THE FREE MOVEMENT OF ALL LINKAGE
- 9. CHECKING, CLEANING, OR REPLACING THE FUEL FILTERS
- 10. CHECKING THE FLAME DETECTION SYSTEM FOR PROPER OPERATION.
- 11. CHECKING ALL SAFETY AND RELIEF VALVES, THE LOW WATER FUEL SHUTOFF, WATER LEVEL CONTROLS, & THE WATER GAUGE GLASS FOR PROPER OPERATION AND CLEANING OR REPLACING IF REQUIRED.

 12. CHECKING AND ADJUSTING ALL FUEL OIL
- PUMP SEALS
- 13. CHECKING THE CONDITION OF ALL COUPLINGS
- 14. CHECKING AND LUBRICATING ALL MOTORS.

VENDOR MUST PROVIDE A 24 HOUR PHONE NUMBER THAT CAN BE USED FOR EMERGENCIES.

INVOICES TO BE BILLED IN ARREARS.

MFG. LIST PRICE LESS ____% DISCOUNT

| 00002 | COMMODITY CODE: 931-99-052033 LABOR, ALL TYPES, NORMAL HOURS | 1 | HR | |
|-------|---|---|----|------|
| 00003 | COMMODITY CODE: 931-99-052034 LABOR, ALL TYPES, OVERTIME. | 1 | HR | |
| 00004 | COMMODITY CODE: 910-99-064651 PARTS & MATERIALS, REPLACEMENT | 1 | LT | |

PAGE TOTAL BID TOTAL

HVAC Maintenance Bid Specs Finance Department Division of Risk Management 777 Office Park Montgomery, Alabama

The Division of Risk Management (Finance Department) owns three buildings at 777 Office Park: 771 South Lawrence Street, 777 South Lawrence Street, and 770 South McDonough Street. There are no maintenance personnel on staff. The Division of Risk Management wishes to contract for periodic inspection, preventive maintenance, service and repair of HVAC systems located in these three (3) buildings. The controllers are manufactured by Distech and Lonworks. Niagara AX is the software used to diagnose equipment problems, to service the existing controls, and to integrate new equipment and systems as may be necessary.

The equipment to be serviced includes:

- 1. Outdoor Heat Pump Units
- 2. Air Handlers
- 3. Packaged Rooftop Units
- 4. Exhaust Fans
- 5. Hydronic Pumps for Heating Systems

An equipment breakdown with filter/belt sizes and quantity is attached.

All bidders must provide a copy of a current City of Montgomery business license.

All bidders must provide a copy of the current EPA Certifications.

All bidders should have a minimum of 5 years of commercial HVAC maintenance experience.

Bidders must furnish references from 3 current commercial customers that have been serviced multiple times within the past year. Furnish name of company, contact person, and a current phone number.

Bidders must be Niagra certified and furnish a copy of the "Certificate of Completion" from Niagara.

Bidders must be insured with a minimum of \$1,000,000 per occurrence and \$2,000,000 general aggregate general liability insurance and provide evidence of insurance with the bid.

All bidders must have Workman's Compensation insurance in accordance with the laws of the State of Alabama and furnish proof of insurance with the bid.

June 2010 Page 1 of 4

Contractor will invoice in arrears for each service call to include all parts, freight, labor, date of service, and a description of work performed.

Contractor will provide a detailed task list (service ticket) to the State at the time the service is completed.

There will be a mandatory site visit. Failure to attend the site visit will disqualify a bidder.

Contractor must be located within 50-100 miles and provide a response time for a non-emergency service within 24 hours. Response time for an emergency call is 1 hour. Upon award of bid, vendor must provide a 24 hour service call number.

The contract will include the following items:

- Annual and Quarterly preventive maintenance service calls.
- Labor rates for service and repairs not included in the routine preventive maintenance service calls.
- Service and repair parts and components not included in the routine preventive maintenance service calls.

A. Preventive Maintenance Service Calls

Contract requires a quarterly preventive maintenance service call to each building. Each service call shall include the following services:

- 1. Travel to and from the service location.
- Visual and mechanical inspection of all systems, units and components at each location to determine operating condition and efficiency. Typical inspection criteria shall include but not be limited to:
 - · Refrigerant charge Annual
 - Air temperature at random discharge registers
 - Condition of heat chambers, burners, flues, etc. Annual
 - Flame, pilot, safeties, and igniter Annual
 - Belt condition, tension, alignment
 - Excessive vibration and/or noise
 - Safety controls Annual
 - Proper combustion and draft
- Preventive maintenance of all systems, units and components at each service location assure proper operation and efficiency, and maximize equipment life

while minimizing unnecessary failures and repairs. Typical preventive maintenance items shall include but not be limited to:

Cleaning:

- Outdoor Coils Annually Coils, as needed but no less than quarterly
- Furnish and replace all disposable filters MERV 7 or greater rating
- Cleaning of all permanent filters
- Fan impellers and blades inspect quarterly; tighten annually
- · Pilot orifices and igniters Clean annually
- Clean & inspect condensate drains/pans/sumps inspect quarterly and clean annually
- Electrical contacts annually
- Burner orifices annually
- Boiler tubes
- Condenser housings screws and panel intact

Lubrication:

- Motors
- Bearings
- Valve Stems leakage quarterly
- Linkages

Alignment/Calibration/Adjustment:

- Belts, alignment and tensioning quarterly
- Couplings
- Safety Controls annually
- Temperature and pressure controls annually
- Electrical connections annually
- Mounting bolts annually
- Clamps/fittings annually
- Refrigerant charge annually
- Water chemicals
- Fuel/Air ration annually
- Gas pressures annually
- Controls and limits annually

Miscellaneous:

- Inspection for worn, failing or questionable parts
- Painting of housings, chases, panels, etc. to prevent corrosion
- Any preventative maintenance activities recommended by the equipment manufacturer

- Any routine service procedures recommended by the equipment manufacturer
- Ant, insect and rodent control in and around condenser housings, electrical
 enclosures, etc. evidences of significant infestation must be brought to the
 attention of the facility administrator immediately.
- 4. All service and/or repair needs discovered during routine testing, inspecting and preventive maintenance operations which are not included in this contract must be brought to the attention of the facility administrator immediately. Contractor will provide the facility administrator a detailed repair proposal including comprehensive estimate for parts and labor based on contract pricing.

Note: Refrigerant and refrigerant oil, whether installed during a routine service call or during a non-routine service call, is to be invoiced as a repair/service part.

B. Labor rates

- Hourly labor rate for a licensed HVAC mechanic, regular hours (Monday-Friday, normal work hours for company such as 8-5, 7-3, 7:30-4:30)
- Hourly labor rate for a licensed HVAC mechanic, overtime hours (all other days and hours, state and federal holidays)
- Hourly labor rate for a licensed HVAC mechanic's helper, regular hours (Monday-Friday, normal work hours for company such as 8-5, 7-3, 7:30-4:30)
- Hourly labor rate for a licensed HVAC mechanic's helper, overtime hours (all other days and hours, state and federal holidays)

C. Parts and Components

 Mark-up percentage for replacement parts and components regardless of the dollar amount of cost

June 2010 Page 4 of 4

| Model (Trane Manufacturer) | Serial # | Tag# | Phy Location of Unit (Roof, Basement, etc) | Area Served | Filter Qty | Filter Qty Filter Size |
|-----------------------------------|-----------|------------|--|------------------------------------|------------|------------------------|
| LPCAD06D4**H5A000000 | | | | | | |
| 01CAD0000 | T09J19332 | EBU-3A-LNW | 1st Floor Mech Rm | 771 North | 2 | 20x25x2 |
| LPCAF06D4**H5A000000 | | | | | | |
| 01CAC0000 | T09J19324 | EBU-4A-LNW | 1st Floor Mech Rm | 771 North | N | 20x25x2 |
| LPCAF03D4**H5B000000 | | | | | | |
| 01CAL0000 | T09J19325 | EBU-6-L | Bsmt. Mech Rm | 777 Basement | _ | 20x25x2 |
| LPCAF10D4**H5C000000 | | | | | | |
| 02EAC0000 | T09J19326 | AHU-3-MCD | 2nd Floor Mech Rm | 770, 2nd Floor West | N | 20x25x2 |
| | | = | | | _ | 16x25x2 |
| LPCAD06D4**H5C000000 | | | | | | |
| 01DAK0000 | T09J19327 | AHU-2-LNW | 1st Floor Mech Rm | 771 West, 2nd Floor | N | 20x25x2 |
| LPCAD08D4**H5D000000 | | | | | | |
| 01EAN0000 | T09J19328 | AHU-8-L | Penthouse Mech Rm | 777, 2nd Floor Southeast | _ | 20x25x22 |
| | | = | | | 1 | 25x25x2 |
| LPCAD08D4**H5D000000 | | | | | | |
| 01DAH0000 | T09J19329 | EBU-1-L | Bsmt. Mech Rm | 777, 1st Floor North, Underwriting | ω | 16x25x2 |
| LPCAD03A4**H5B000000 | | | | | | |
| 01CAM0000 | T09J19330 | EBU-2-L | Bsmt. Mech Rm | 777, Basement, Consumer Credit | _ | 20x25x2 |
| LPCAD06A4**H5A000000 | | | | - 1 | | |
| 01CAD0000 | T09J19331 | EBU-3-L | Bsmt. Mech Rm | 777, Basement, Consumer Credit | N | 20x25x2 |
| LPCAD08D4**H5D000000 | | | | | | |
| 01EAP0000 | T09J19333 | AHU-9-L | Penthouse Mech Rm | 777, 2nd Floor, Southwest | _ | 20x25x2 |
| | | = | | | _ | 25x25x2 |
| LPCAD08D4**H5B000000 | | | | | | |
| 01DAH0000 | T09J19334 | AHU-4-L | Basement Mech Rm | 777, 1st Floor Southeast | 3 | 16x25x2 |
| LPCAD08D4**H5B000000 | | | | | | |
| 01DAH0000 | T09J19335 | AHU-5-L | Basement Mech Rm | 777, 1st Floor Southwest | 3 | 16x25x2 |
| LPCAD10D4**H5B000000 | | | | | | |
| 02FAK0000 | T09J19336 | AHU-1-LNW | 1st Floor Mech Rm | 771, 2nd Floor, North, Lg Conf Rm | _ | 24 x 24 x 2 |
| | | = | | | 2 | 16 x 24 x 2 |
| LPCAF12D4**H5A000000 02FACA000 | T09J19320 | AHU-2-MCD | 1st Floor Mech Rm | 770. 1st Floor East | 2 | 20x25x2 |
| | | = | | | _ | 16x25x2 |

| Model (Trane Manufacturer) | Serial # | Tag # | Phy Location of Unit (Roof, Basement, etc) | Area Served | Filter Qty | Filter Qty Filter Size |
|-----------------------------------|-----------|-------------|--|-------------------------------------|------------|------------------------|
| LPCAD06D4**H5A000000 01CAD0000 | T09J19332 | EBU-3A-LNW | 1st Floor Mech Rm | 771 North | 2 | 20x25x2 |
| Model (Trane Manufacturer) | Serial # | Tag# | Phy Location of Unit (Roof, Basement, etc) | Area Served | Filter Qty | Filter Size |
| LPCAF12D4**H5A000000 02FACA000 | T09J19321 | AHU-4-MCD | 2nd Floor Mech Rm | 770, 2nd Floor East | 2 | 16x20x2 |
| | | = | | | _ | 16x25x2 |
| | | = | | | N | 20x20x2 |
| | | = | | | _ | 20x25x2 |
| LPCAF10D4**H5A000000 02EAC0000 | T09J19322 | AHU-1-MCD | 1st Floor Mech Rm | 770, 1st Floor West | 2 | 16x20x2 |
| | | = | | | _ | 16x25x2 |
| | | = | | | 2 | 20x20x2 |
| | | = | | | _ | 20x25x2 |
| LPCAF08D4*H5E0000000 1EAL0000 | T09J19323 | AHU-7-L | Penthouse Mech Rm | 777, 2nd Floor, Legal, Risk Mgr | _ | 20x25x2 |
| | | = | | | _ | 25x25x2 |
| YHC043A3RMA**B0C000 00B000*** | | RTU-L1 | Roof | 777, 2nd Floor, Center Reception Ar | 2 | 20x25x2 |
| TTA180C300G:15 Ton | | ACCU-4-MCD | Roof | - 01 | | |
| 2TTA3036A3000A:3 Ton | | | | | | |
| 2TTA3036A3000A:3 Ton | | ACCU-2-L | Roof | EBU-2-L | | |
| Unitary | | ACCU-6-L | Roof | EBU-6-L | | |
| 2TTA3060A3000A:5 Ton | | | | | | |
| 2TTA3060A3000A:5 Ton | | ACCU-2-LNW | Roof | AHU-Z-LNW | | |
| Unitary | | ACCU-3-L | Roof | EBU-3-L | | |
| 2TTA3060A3000A:5 Ton | | | | | | |
| Unitary | | ACCU-3A-LNW | Roof | EBU-3A-LNW | | |

| Model (Trane Manufacturer) | Serial # | Tag # | Phy Location of Unit (Roof, Basement, etc) | Area Served | Filter Qty | Filter Qty Filter Size |
|-----------------------------------|-----------|----------------|--|---------------|------------|------------------------|
| LPCAD06D4**H5A000000 01CAD0000 | T09J19332 | EBU-3A-LNW | 1st Floor Mech Rm | 771 North | 2 | 20x25x2 |
| Model (Trane Manufacturer) | Serial # | Tag # | Phy Location of Unit (Roof, Basement, etc) | Area Served | Filter Qty | Filter Qty Filter Size |
| 2TTA3060A3000A:5 Ton | | ACCIL AA I NIM | Doof | EBIT AN I NIM | | |
| Unitary TTA120B300:10 Ton | | ACCU-4A-LNW | Roof | EBU-4A-LNW | | |
| Unitary | Secure | ACCU-1-MCD | Roof | AHU-1-MCD | | |
| TTA180B300:15 Ton Unitary | | ACCU-2-MCD | Roof | AHU-2-MCD | | |
| TTA120B300:10 Ton Unitary | | ACCU-3-MCD | Roof | AHU-3-MCD | | |
| TTA120B300:10 Ton | | | | | | |
| Unitary | | ACCU-1-LNW | Roof | AHU-1-LNW | - 1119 | |
| TTA090A300:7.5 Ton | | | | | | |
| TTA090A300:7.5 Ton | | | | | | |
| Unitary | | ACCU-4-L | Roof | AHU-4-L | | |
| TTA090A300:7.5 Ton | | 9 | Dock | VIII E I | | |
| TTA0904300:7 5 Ton | | 1 | | | | |
| Unitary | | ACCU-7-L | Roof | AHU-7-L | | |
| TTA090A300:7.5 Ton | | | And the control of th | | | |
| Unitary | | ACCU-8-L | Roof | AHU-8-L | | |
| TTA090A300:7.5 Ton | | 200 | | \L 00 | | |
| o marij | | | | | | |
| | | | | | | |

| | | 771 North | 1st Floor Mech Rm | | C09214995 | |
|-------------------------|------------|---------------------------------|--|------------|-----------|------------------------------------|
| | | 777 1st Floor Southeast | Basement Mech Rm | | C09215221 | PNCH1000 Boiler |
| | | 770, 2nd Floor East | 2nd Floor Mech Rm | | C09215220 | PNCH1000 Boiler |
| Filter Gity Filter Size | riller Giy | Area Served | Basement, etc) | ıag# | Serial # | Manufacturer) |
| | | | Phy Location of | = | | Model (LAARS |
| | | 770, Room 113, 1st Floor | | HP-3 | | |
| | | 770, Conference Rm 1st Floor | | HP-2 | | |
| | | 770, 1st Floor, North Workroom | | HP-1 | | |
| | | 770 Bldg, Second Floor Workroom | | HP-4 | | |
| ?? | ?? | 777, Computer Room, 2nd Floor | Roof | | 8ZU01168A | PUZ-A18NHA2 |
| Filter Qty Filter Size | Filter Qty | Area Served | Phy Location of Unit (Roof, Basement, etc) | Tag # | Serial # | Model (Mitsubishi Manufacturer) |
| 20x25x2 | 2 | 771 North | 1st Floor Mech Rm | EBU-3A-LNW | Т09J19332 | LPCAD06D4**H5A000000 01CAD0000 |
| Filter Qty Filter Size | Filter Qty | Area Served | Phy Location of Unit (Roof, Basement, etc) | Tag # | Serial # | Model (Trane Manufacturer) |